

1

3/6

"Tural"

Sent to Chief Surveyors 30. 11. 16

Received from Chief Surveyors

VESSEL'S NAME Steel SS P.L.M. No 5 Report Detroit No. 20

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey 1<sup>st</sup> Survey When due

✱ 100 A-1 (Steel)  
1 DK (Steel) Topside Tanks  
Cell DB 209' 595L. Topside Tanks 382L. FRT. 180C. A.P.T. 50C.  
FK. 4BH. Cen. area. F 25. Mely aft.

The Certificate of Classification to be endorsed  
"Cargo battens not fitted." and the same  
notation to be printed in the Register Book.



© 2020

Lloyd's Register  
Foundation

002127-002137-0091