

KINSALE

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME

Stet S.S. GORIKWA

Report

Gls

No. 41725

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey \_\_\_\_\_

When due \_\_\_\_\_

Hand pumps to the hold have been dispensed with for the present but it is concluded the Owners are agreeable to fit same or their equivalent if required

❖ 100-A-1. (Steel)

1 Deck (Steel)

Cell DBUE 21' x 120' 193t, FPT 28t, APT 4t

FK 3BH, Cam, Luby to A/C, P74' F22' Mchly aft

Date of build 2.22.

Certificate of Classification, to be endorsed  
"no buttens not fitted," and the same  
to be printed in the Register Book.



© 2020

Lloyd's Register  
Foundation

002127-002137-0106

Handwritten signature and date: 16-7-22