



Lloyd's Register of Shipping,

55, Fawcett Street,

Sunderland, 8th September 1930.



Reference

Dear Sir,

With reference to your Classing letter of the 5th instant, regarding the M.V. "LONGWOOD" Sunderland Report No.30449. I have to state that the tenacity of the boiler shell plates and straps is 29/33 tons and not 28/30 as noted on the Report. There are three lubricating oil pumps of Weir type, two working and one spare, each pump coupled ready for use, the size of each pump is 9" x 8" x 18" stroke with a capacity of 44 tons per hour and all connections fitted according to the Rules. I regret that this information was omitted from the Report.

I am, Dear Sir,

Yours faithfully,

The Secretary,
LONDON.



© 2020

Lloyd's Register
Foundation

002165-002173-0168

002165-002173-0171

002165-002173-0171

Flat Plate Keel Angles

4 4 50

Spacing.....

Referred to the Chief Engineer Surveyor.

has

19 SEP 1930

Also for Mr. S. A. Hill to note.

(S)
15/9/30

RECORDED

INDEXED



© 2020

Lloyd's Register
Foundation



TELEPHONE: 173 S...

56.728

Do. of space on
business trans...

1 tonnage D...

0046500