

S.S. "Machado."
ex "Torbritt"

{ Ans. 8685.
" 8695.

This vessel's machinery has been built under special survey.

Being to a report of shortage of water in the fore-boiler during the trial trip the same has been examined, and has been found in good condition.

The I.P. cylinder was also found cracked in way of slide valve chest, and this has been repaired by the fitting of a patch.

It is submitted that
this vessel is eligible for

THE RECORD. \pm L. M. C. - 3.22.

subject to the I.P. cylinder being specially examined or renewed before the end of March 1923.



© 2020
Ans. 29/3/22
Lloyd's Register
Foundation

002174-002183-0196