

F.E.

by Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME *Stl S* NOTRE DAME DE FRANCE Rpt. *Indb* 14370  
*Indb* No. 14369

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

*Long*  
 Transverse No. 2288 Depth "d"  
 Naming: Table No. Description *angle frames as approved*  
 Longitudinal No. 6200  
 Proportions Length 9.8  
 Depth =  
 Deck Sheerstrake *as approved*

## Revised Rules

Vessel placed in drydock and some damage through collision repaired to surveyor satisfaction.

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A.1. (Steel). Steam Hawker  
 1 DK.

Wing tanks in ER 10T, Cell D. By 33' 33.5.

BK 7 1/2", 3 B.H., Cem, Ploys A/C.P.

Q 78", F 26'.

It is concluded the size of the ~~propellers~~ <sup>stern frame</sup> is approved but the surveyor should be requested to state if this is so.

002194-002205-0235