

Sld 34722

Armillia

complete LMC survey has been held.
th screw shafts examined, the starboard shaft
lauged on account of worn liner. Port liner
revised. all plain tubes renewed in donkey boiler
considerable wear & tear repairs effected
BS held.

It is submitted that this
vessel is eligible for THE
RECORD. + LMC 7.47. DBS 7.47

Port 5.47

Starb S. N. 5.47

new 7th form required

Robt 22/7/47

Lloyd's Register
Foundation

1910-1122000-0164