

(1m,5,4.)

1.

Sent to Chief Surveyors 26.7.04

Received from Chief Surveyors _____

VESSEL'S NAME Ste. S. S. "G. Player" Report Els. No. 21952

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Fit entry When due _____

± 100 A 1 ('Steel')

1 DR (2m) Wall bulk

W.B = All DB f103'1626 FPT 586 APT 86

FK9BK1 1/2 3BH Cam. Plogh AYCP P19' Q83' B12' F25' Melby Aft.

C.H.
26/7/04



© 2021

Lloyd's Register
Foundation

002222-002228-0222

quarter, tween DKS.,
in Hold

Angle on chitto.
Tie Plates / plates on mid line for 6 ft 3 1/2 A1