

"PORT RELIANCE"

It is submitted the Liverpool Surveyors be informed in connection with the provisional anchor certificates issued for this vessel, that the anchors were subjected only to drop test, tensile and bend tests and that no statutory tests were carried out. In the special circumstances, these craft have been accepted, and the figure (1) assigned, with the proviso that they shall be submitted to the statutory test when the present state of emergency has passed.

As regards the chain cable, it would appear from a letter received from the Vancouver Surveyors, dated 28th September 1942, that this cable has been tested in accordance with the Society's rules, and that an <sup>cable</sup>~~anchor~~ Certificate No. 1548 was issued by the Society's Surveyors stationed at Cleveland U.S.A.

*SB* 14.1.43.



© 2020

Lloyd's Register  
Foundation

002232-002240-0130