

4P+5. Bridge Tween deck no valves fixed

Official No. 142611

in SEPTEMBER/OCTOBER, 1932.

The flush bunker scuttles have been dispensed with at some previous occasion and riveted plate patches fitted on deck.

SMALL HATCHES.

BRIDGE TWEEN DECKS.

Side bunkers 4 of 6'6" x 3'0" x 9" B.A.Coaming, 2" rest angle, cleats 22" apart, 2 $\frac{1}{2}$ w. covers, 1 tarpaulin each hatch. The forward two hatches have been dispensed with from original report at some previous occasion.

For'd end No.2,23" x 22" x 20" coaming, $\frac{3}{8}$ " thick, 3" rest angle, cleats 10" apart, 2 $\frac{1}{2}$ w. covers												
2 tarpaulins.												
Aft	"	No.3	23"	x	19"	x	20"	"	"	"	"	"
"	"	"	4	22"	x	21"	x	20"	"	"	"	"

(Gls., Oct., 1937).

1 Feb
13/1/30