

FEB -1 1941

Index No. _____

Hd 3682

Lloyd's Register of Shipping.

Ship's Name "MATAROA."

Official No. 144814

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines

in _____

This vessel has been requisitioned for Government service at this time, and at the Owners' request it has been noted that original sidelights in the No 2 Upper tween decks, and which had been permanently closed up by fitting efficient spigot plates, have been opened up again to comply with the requirements for her present emergency service.

These sidelights of strong construction and fitted with hinged deadlights as originally.

NOTE:- The lower edge of the sidelights at this position

is approximately 10'-0" above the Plimsoll mark. D.S. Forreth

NOTE:- This information has been appended to the copy of the C11 on board ship.

002269-002278-0151

noted
S.W.B.

4 FEB 1941

28/1/2021

Lloyd's Register
Foundation