

27
s/s Mirandella Dis. 1660.

It is submitted before this case receives consideration, the Lisbon Surveyors should be requested to forward a First Entry Report on the boilers.

Chrs 23/6/21

I.W.D.
21/6/21



© 2020

Lloyd's Register
Foundation

vessel placed in dry dock, and the requirements of the Rules for a

vessel not built under survey carried out and minor repairs effected