

to Chief Surveyors.....

Received from Chief Surveyors.....

SHIP'S NAME "MONKSVILLE"

REPORT

Lw.

No. 144/29

For the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from sub-Committee's Report, 24/5/92.).

Nature of Survey.

Examination for fastenment of S.S.

When due

3, 56

Noted

Subject to forecandle & R.Q. deck plating over A.P. tank (corroded).
and to hull plates Nos. 5 & 6, etc. (set up maximum 17") being specially examined
& dealt with as necessary & to permanent repairs to R.Q. deck sheerstrake plate
No. 2, etc. (ss), at the S.S.

Endorsement of class/B)

Indents in shell plating, etc. in way of No. 2 hatchway
(ss) & B.3/ps). Hull plates No. 2 also shell plates
A. 7 & 8 & B. 7/55) set in ✓

The proposal to postpone the S.S. until 7, 56
has been approved.



© 202

Lloyd's Register
Foundation

002289-002297-0033