

S.S. "MORETON BAY".

In reply to a request that the certificate of test for the cable shackle, recently placed on board the above vessel, should be sent to this Office, the Owners' Representative states, per telephone, that the certificate in question does not appear to be in their possession, and suggests that in the circumstances the classification certificates might be endorsed to the effect that the shackle has been examined by the Society's Surveyors but the marks thereon have not been compared with the certificate of test.

J. H. C.

6th. December, 1921.

*Report in Booklet
1st Dec 1921*



© 2020

Lloyd's Register
Foundation

002289-002297-0117