

by Chief Ship Surveyor 15. 9. 17

Received from Chief Ship Surveyor _____

'S NAME S. S. Rapidol Rpt. Hpl No. 15397

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Survey _____

It is submitted that before this case receives consideration the Surveyors should be requested to state as follows:

1. Whether the class should not be 100A.1. for Government Service
2. Whether they are correct in reporting that the hulls of the keel plate are overlapped
3. Whether a shell wire 160 fms 5" dia is supplied in lieu of steam chain

Lr Hpl 17/9/17

M
17.9.17



© 2020

Lloyd's Register
Foundation

002289-002297-0242