

1 NOV 1944

Lloyd's Register of Shipping.

Ship's Name S/S "RIBERSBORG"


Official No. 7103

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines in _____

No. 2 hatchway, hatch beams:-

Number 2 ✓

Spacing 2160 mm. ✓ $7' - 10\frac{1}{2}"$

| | | |
|-----------|--|---|
| Scantling | EW  | 230 x 17 ✓ $9 \times .67$ ✓ |
| | | 450 x 9.5 ✓ $17\frac{1}{2} \times .375$ |
| | | 230 x 17 ✓ $9 \times .67$ |

$\frac{3}{4} = 125$
Rule 93

Bearing surface 75 x 25
3 x 1

Helsingborg, 11th October, 1944.

..... *O. J. J. J.*
Surveyor to Lloyd's Register.

S.E.B.
2.11.44

