

t. 8.

For the information of Surveyors and the Committee only.

Received at

Office

19

# Lloyd's Register of Shipping.

Order: 40366/St  
Post: 4486

(Report on Vessel No. \_\_\_\_\_ Port \_\_\_\_\_)

No. 1185 SHIP ~~FORGINGS~~ OR CASTINGS.

I have to report that the undermentioned ~~propeller~~ Steel ~~propellers~~ Castings, manufactured by Messrs. Witkowitz Bergbau & Eisenh. Gew. of Witkowitz for the Vessel No. 596, being built by Messrs. N.V.C. Giessen & Zoonen of Krimpen have been inspected by me as set forth below and found to be, so far as can be seen, 2 propeller brackets, sound and free from defects, sound and free from defects.

Work on ~~propellers~~ Castings.

Lloyd's  
No. 3516 9388/89  
HK.15.2.29

Vienna, 18th February 1929

*Hans Kolbow*

	1 propeller bracket <del>STEM FRAME</del>	1 propeller bracket <del>RUDDER FRAME</del>	STEM.
Material*	Siemens Martin Steel		
How made	cast		
annealed	annealed		
Dimensions	to sketch		
Progress on Inspection	almost finished		
Date when Inspected	17.1; 15.2.1929		
CASTINGS.	No: 9388		
Tests on Standard Test Pieces.	No: 9389		
Tensile Test— Tons per square inch	29.1    28.6	32.4    31.0	
Extension per cent. ...	32.9    36.8	34.2    35.5	
Cold Bending Test— Angle before fracture	120 degree good		
Drop Test— Height from ground ...	dispensed with		
Hammering Test— If made according to Rules and found satisfactory ...	satisfactory		

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Fee (if any chargeable) £ : :

To be paid at VIENNA

\* If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

n.10.27. T.

002330-002334-0158

8m.2.27.



© 2020

Lloyd's Register  
Foundation