

where tested and
intendent.

Neon.

It is concluded that the
main and auxiliary bilge pumps have
no connections to the cargo tanks
& coffer dams but this should be
confirmed.


Dr. Rot. 29/11/29

R.

27/11/29

27/11/29

ho
See 27/11/29



002330-002334-0165

(per Section 28.)

Travelling Expenses (if chargeable).....

2 of £ 00

Received by me,

28.11.29

29/11/29

Committee's Minute

FRI 29 NOV 29

Engineer Surveyor to Lloyd's