

LLOYD'S REGISTER OF SHIPPING,

425 KING STREET

JACKSONVILLE, FLA.

609 Northern Blvd
Sunset Park

LLOYD'S REGISTER
NEW YORK

REC'D MAR - 7 1921

ANS'D _____

Wilmington, N. C.
4 March 1921.

French Egg
Dear Sir,

With reference your letter of 25th February
on the S. S. "Pearlton", I beg to advise that the
thickness of the stiffeners on oil tight bulkheads, the spacing
of the end longitudinal frames, the thickness of the centre
girder in the boiler space, the number of rivets in tracks
of bulkheads, the riveting in longitudinals, and the
stitch of the quadruple riveted butts of the upper deck
stringer plate are as approved, also that the riveting in
the keel frame is as required.

A hand pump is fitted for draining the fore peak
tanks.

Yours Very Truly
W. Hamilton

© 2020

Lloyd's Register
Foundation

002340-002351-0084