

1

Everaga

"Baronina"

Sent to Chief Surveyors 1. 11. 11

Received from Chief Surveyors

VESSEL'S NAME *Sheels Glenloy*

Report *Erk*

No. 16122

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Nature of Survey

1st Engr -

When due

* 100 A-1. (Steel)

1 DR (ptt)

WB = Cell 2. B a + u 137 + 160 8796. A.P.T. 786

FK. 6 BM. Com. Slips a + r. P. 28. B. 93 F. 41.

SM

1. 11. 11

~~It is concluded the rivets in hulls of keel plate, & of the sheerstrake where double straps are fitted are spaced 4 1/2" apart & not 5" as stated~~



© 2020

Lloyd's Register Foundation

002340-012351-0184