

135 FMS 98-0-13.
 Steering Gear, Steam *BY DONKIN & CO. LTD* NEWCASTLE-ON-TYNE No 6296 Steering Gear, Hand *TILLER*
 Boats *WOOD CUTTER* Steering Chains, Size and Test *15 DIAS AND 10 1/2 TONS TEST.* Windlass *BY G*
 Ceiling in Holds, thickness and material *3" OAK AND 2 1/2" PITCH PINE.* Cargo Battens, thickness, material and spacing *2" PINE 5" CO*
 3"

(Received at London Office... 30 SEP 1935...)

No. *3080* Port *Hull.* Date *27th Sept. 1935*
 We request that the *Steel* Steam Trawler Building
 for *Maxine Steam Fishing Co Ltd* by *Cook, Welton & Gemmell Ltd*
 of *✓* Tons. Length, *155.7* breadth, *26.15* depth, *14.16*
 may be Specially Surveyed while building (*100 A.1. Steel Steam Trawler*) If for a particular term or class, state the same.

We hereby engage to pay the established Special Survey Fees in accordance with the Society's Rules for Trawlers as follows, also the fees for inspection of installation of Electrical Fittings as set forth in the Society's Rules for Electric Fittings.

For trawlers built under the special superintendence of the Surveyors (to entitle them to the distinctive mark ∇), 2s. per ton gross. No fee to be less than £10.

For engines and boilers built under the special superintendence of the Surveyors (to entitle them to the distinctive mark ∇ in red) :-
 Five shillings per Nominal Horse Power. No fee to be less than £9.

he Nominal Horse Power for regulating survey fees on engines and boilers to be determined as described in Section 29.
 Entry Fees as per Section 28 are additional to the above charges.

In exceptional cases an additional charge will be made according to the service performed, and in all cases where travelling expenses are incurred by the Surveyors in connexion with the above services, they are to be defrayed by the parties interested.

In no case can the vessel be classed until all fees, travelling expenses, &c., due thereon are paid.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that :-

While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.

No. *604* in Builder's Yard. Manufacturers of Engines } *Messrs Amos & Smith Ltd.*
 Ditto of Boilers } *Hull*
 Signature *A. D. Campbell*
 CHIEF DRAUGHTSMAN.

Authd
 the Secretary,
 Lloyd's Register of Shipping,
 71, Fenchurch Street, London, E.C.3.

Special Survey Fee... £ *43-14-0*

Travelling Expenses, if any £ : *8-7*

State whether the Vessel has been built under Special Survey *YES.*

002362-002373-001
 24 JAN 19 1935
 Received by me,
11-2 1935
 12/2

© 2020

Lloyd's Register
 Foundation
 I am of opinion the Vessel should be Classed
 ST

Signature