

Ceiling in Holds, thickness and material

NONE.

Cargo Battens, thickness, material

Cargo Hatchways.—(Upper Deck)

NONE.

Thickness of Hatches

Size of Hatchways No. 1 (E-1)

No. 5

Req. 1 (Tr.).

(Received at London Office.....)

120 SEP 1941

No. 3292. Port

Hull.

Date 18<sup>th</sup> Sept. 1941

We request that the Single Screw Steam Trawler Building

for The Admiralty by Cochrane & Sons Ltd., Selby.

Tons. Length, 146'6" B.P. breadth, 25'0" MLO depth, 14'0" MLO.

to be Specially Surveyed while building ( 100 A-1. "Trawler" ) If for a particular term or class, state the same.

We hereby engage to pay the established Special Survey Fees in accordance with the Society's Rules for Trawlers as follows, also the fees for inspection of installation of Electrical Fittings as set forth in the Society's Rules for Electrical Equipment.

Trawlers built under the special superintendence of the Surveyors (to entitle them to the distinctive mark ✕), 2s. per ton gross. No fee to be less than £10.

Engines and boilers built under the special superintendence of the Surveyors (to entitle them to the distinctive mark ✕ in red):— Five shillings per Nominal Horse Power. No fee to be less than £9.

The Nominal Horse Power for regulating survey fees on engines and boilers to be determined as described in Section 29.

Entry Fees as per Section 28 are additional to the above charges.

In exceptional cases an additional charge will be made according to the service performed, and in all cases where travelling expenses are incurred by the Surveyors in connexion with the above services, they are to be defrayed by the parties interested.

In no case can the vessel be classed until all fees, travelling expenses, &c., due thereon are paid.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

1245 in Builder's Yard.

Manufacturers of Engines

Amos & Smith Ltd. See Hull etc. Chas. D. Holmes & Co Ltd, Hull

Ditto of Boilers

FOR COCHRANE & SONS LTD.

the Secretary,

Signature

Lloyd's Register of Shipping,

71, Fenchurch Street, London, E.C.3.

D. R. Cookham DIRECTOR. acd

The amount of Entry Fee..... £ : ✓ :

FEE FOR CLASSIFICATION AND

Special Survey Fee..... £ 110 : 0 : 0

SUPERVISION OF SPECIFICATION.

Fees applied for,

22 JUL 1941

Received by me,

002362-002373-0152

Lloyd's Register

Foundation

(Special notations, where part of)