

ed by Chief Ship Surveyor

Received from Chief Ship Surveyor

12/10/21

SHIP'S NAME Steel S.S. "EDAM". Rpt. Ant. No. 11705

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Remarks of Surveyor

The Antwerp Surveyors report this vessel has sustained damage to the stem and stem plating through collision.

The damaged part of the starboard hawsepipe has been cut away in order to allow the anchor to be dropped if necessary, and the Surveyors recommend that repairs be carried out on the vessel's arrival at Rotterdam.

It is submitted the Rotterdam Surveyors be advised.



© 2020

Lloyd's Register
Foundation

12. 10. 21.

002385-002400-0014

Rot 7/10 Dam & F.E.

Ask Rot for F.E.