

Bls

Report No.

31750

It is submitted that further action in the case is unnecessary until this boiler is fitted on a classed vessel.

[Signature]

Date

22.8.12



© 2020

Lloyd's Register
Foundation

[Signature]

002385-002400-0071

ter spaces *13 1/2"*

Working pressures by rules *130*

Girders to Chamber tops: *M*