

F.E.

Received by Chief Ship Surveyor 15.9.14 Received from Chief Ship Surveyor _____
 VESSEL'S NAME MS S. Crullus Rpt. Mdb No. 8617

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 33.66 Depth "d" 11.0
 Framing: Table No. 3 page 9 Description Single Angle
 Longitudinal No. 3769
 Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{9.08}{}$

Deck Sheerstrake .50 of an inch in thickness
 instead of .37 as required.

It will be observed that the weight of the 3rd anchor is 6 lbs less than required by Rule but the collective weight is 1 gr 6 lbs in excess.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed :- 100 A.1. (Steel) Steam Trawler as recommended.

:- 100 A.1 (Stl.) "Steam Trawler."
 1 Stl.

RK 7 1/2 " 2 B.H. Com. Loya & Co. P. 67.

M. W. M.
 15.9.14

