

Headrott

It is submitted the Malmo
Surveyor be requested to state whether
each lubricating oil pump is
of sufficient capacity to supply both
main engines under working conditions
whether the connections are so
arranged that either pump can
supply both or either main engines.

Clg. Mr. Jones - 10/9/29

B.A.

7/9/29

Lloyd's Register
Foundation

002385-002400-0228