

F.E.

by Chief Ship Surveyor

Received from Chief Ship Surveyor

L'S NAME

Shells Export

Rpt.

Ans

No. 7604

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

42-5

Depth "d"

Framing: Table No.

3 page 10

Description

Single angle as approved.

Longitudinal No.

7694

Proportions

Length

Depth =

Deck Sheerstrake

The Rotterdam Surveyors report the Survey has been

Completed.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100 A-1 (Steel) as recommended.

{ pl-wood pl- }  
10% (Steel) { Wale etc.

Cell 513 f 103 1376 F.P.T. 466 A.P.T. 456

E.K. 3 B.H. Cam. A.C.P. Q 52. B 64' F 19' Mchly abt.

30-10-18

It is suggested that the Dampier pump has been tested  
but the Rotterdam Surveyors should state if this is so.



© 2020

Lloyd's Register  
Foundation

002401-002409-0005