

Vessel's Name S. S. "L U R C H E R".

Official No. \_\_\_\_\_

No. in Reg. Book \_\_\_\_\_

Port of Registry (For Foreign Vessels) \_\_\_\_\_

3m, 8, 21.

1

Sent to Chief Surveyors \_\_\_\_\_

N.N. "UKSTER COAST" Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Steel S.S. "Lurcher" Report Gls. No. 42310.For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey First Entry. When due \_\_\_\_\_✱ 100A1 (Steel) "Shelter Dk with Freeboard."  
10K (Stl) + Shelter Dk (stl).

Cell DB u E 21' f 126' 201t. FPT 34t APT 19t.

FK. Collision BH to Shelter Dk, 3BH to Upper Dk. Cms. Lloyd's ACP.

2-3  
12-11M A.W.J.  
24/11/22.

Is fee paid? \_\_\_\_\_


Form for Certificate \_\_\_\_\_

Instructions \_\_\_\_\_

Date \_\_\_\_\_

Certificate written \_\_\_\_\_

Noted for posting \_\_\_\_\_



© 2020

002410-002417-0114

Lloyd's Register  
Foundation