

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Stl Se TALUNE Report Gl No. 50179**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required, and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey 1st Entry When due Revised Rules


✠ 100A.1. (Steel)

10" (Stl), 2" D" (Stl) in forward hold.

Cell D.B. 258' 5985, Tanks in way of tunnel 2775, F.P.T. 785, A.P.T. 535

F.K. duct Keel forward of Machinery space, 5 B.H, 11 cm, Claydo A/C P


P.B. 165', F 50'.



[Signature]

[Signature] 30

002421-00434-0008



© 2020

Lloyd's Register
Foundation