

nt to Chief Surveyors.....

Received from Chief Surveyors.....

SHIP'S NAME "BEN ELLAN" REPORT Liv. No. 156063

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

ature of Survey Docking: Grounding damage
repairs. ~~W. L. L. L.~~

N O T E D.


SUBJECT to set up bottom shell plating below coal bunker (p & s) being specially examined and dealt with as found necessary by the next drydocking.

INSERT IN S.R.L. APPENDIX.
(Rudder stock twisted 32° (1,61)).

C.S.S. Records Dept.
to note.



© 2020



Lloyd's Register
Foundation

002435-002441-0158