

Report to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel & Lk CABLE ENTERPRISE Report Yls No. 43660**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey 1st Entry

When due

✠ 100 A. I. (Steel) " with freeboard"

2 SKs (Weather SK ft Stl - Leaks, 2nd SK steel - ws)

Cell D.B. & E 26' / 100' 151t. F.P.T. 12t, A.P.T. 18t.

F.K, 5 B.H (2 B.H to 2nd SK) cem, Lloyds A & CP.

Noted Noted




B 40'

© 2021

J.P. / 23. 5. 24

It is concluded that the owners consent has been obtained to the vessel being built under the Revised Rules, but the Surveyor should be requested to state if this is so.

002442-002448-0152



Lloyd's Register Foundation