

18 JUN 1959

Received from Chief Ship Surveyor

SHIP'S NAME "BLUEWATER" AR. REPORT No. 6796.

Outstanding Conditions of Class: SUBJECT to indented bottom shell plating (p & s) being examined and dealt with as necessary next S.S. and to indented shell plates Nos. 6, 7 & 8, 2nd strake below sheerstrake (p.s. from aft) being specially examined and dealt with as found necessary next S.S. ACTION IS DEFERRED FOR S.S.

Endorsement of Class (B) (As before of ~~XXXXXX~~ None)

Surveys due: SPECIAL SURVEY (D) became due 3,58. Postponement until 3,59 approved 7,58. Further postponement until 10,59 NOT agreed to but modified Special Survey valid for 1 year approved 3,59.

Nature of Present Survey: (Afloat and in dry dock)

Modified S.S.; W & T repairs;

Special Features: -

Interim Certificate in order (Yes-~~NO-NONE~~)

Items Outstanding: (If any for S.S. or A.S.) -

to be completed by:

Recommendation: SUBMITTED record of 'DS 5,59' & the Notation of 'S.S.(M)(1yr) Nap.5,59' be assigned as recommended SUBJECT as above and to 15 fms. of chain cable being supplied at the earliest opportunity.

DS 5,59. S.S.(M)(1yr) Nap. 5,59. Subject.

IN S.R.L. APPENDIX.

Shell plates C.2 & 3 (p.s.a) Shell plate in way of E.R. bunker (p.s) indented.



© 2021 Lloyd's Register Foundation

Handwritten signature and date: 29/5/59