

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, Fen, London

Telephone: ROYal 9166

21st February, 1958.

Dear Sirs,

Steamer "BALTKON"

With reference to my letter of the 13th December last, I have to inform you that the Society's Surveyors at Newcastle have reported that the Main Boiler Survey was partly held last month. To complete this survey the safety valves of both boilers remain to be adjusted.


It is noted from the report, however, that on recommission of the ship the boilers will be opened up for re-examination and the screwshaft examined.

The main condenser water box was examined on this occasion, and some repairs carried out, but it is recommended that this water box should be re-examined by the end of January, 1959. The Committee have continued the class subject to this matter receiving attention by that time.

Yours faithfully,

Assistant Clerk to the  
Classification Committee.

Messrs. John Carlbon & Co., Ltd.,  
Yorkshire Insurance Buildings,  
Lowgate,  
Hull.



© 2020

002449-002456-0011  
Lloyd's Register  
Foundation