

4E

The class is subject to the main condenser waterbox being specially examined before the end of 1.58.

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

13 FEB 1958

SHIP'S NAME "BALTKON"

REPORT

Nwc.

No. 115021

MBS due 1.58, now partly held.

SRL : The main condenser waterbox specially examined. Some repairs carried out. The Surveyor recommends the main condenser waterbox be re-examined by 1.59.


IT IS SUBMITTED that this vessel <sup>will be</sup> ~~is~~ eligible for THE RECORD, MBS 1.58, on completion of the Survey, subject as now recommended.

To complete the MBS : Safety valves of both boilers to be adjusted.

It is stated the vessel is now laid up till June/July 1958, and it is stated that the boiler will then be opened up for re-examination and tailshaft survey carried out.

10.2.58.

002449-002456-0012



© 2020

Lloyd's Register  
Foundation