

Size of opening in
2 1/4
No. and diameter of
of rivet holes and pitch
boiler heater be shut off and
boiler
Working pressure as per
Hydraulic test pressure:
rain cocks or valves fitted
description,
Manufacturers
DIRECTOR
ed herewith 17.6.37
made
parts of the rule
was found
made
essel, examined
with rule
st.
sw.

Built at

COPY.

C.3144.

Lloyd's Register of Shipping.



Port GRIMSBY.

10th November, 1938.

This is to Certify that

A. SMELLIE,

the undersigned Surveyor to this Society did at the request of Messrs Ruston & Hornsby Ltd., attend their works on the 24th June, 1937 and subsequent dates, for the purpose of surveying during construction a 48 B.H.P., 4 stroke cycle, single acting oil Engine, designated No.191594 having 5 cylinders 5 3/8" diameter and 8" stroke.

This Engine and its accessories have been constructed and tested in accordance with the Society's Rules. This Engine has been tested under full power in the shop and found to work satisfactorily.

Identification marks:-

LLOYD'S
3283
21.10.37.
A.S.


Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Rpt. 10.) 20m, 7.38.

002449-002456-0106



© 2020

Lloyd's Register
Foundation