

Received from Chief Ship Surveyor

119 JAN 1959

HIP'S NAME  
AR.

"BEECHER ISLAND"

REPORT

Fal.

No. 13409.

Outstanding Conditions of Class: Subject to rudder being specially examined and dealt with as necessary at next drydocking and to a bower anchor and chain cables (p.s.) being ranged, examined and verified in accordance with Rule requirements next drydocking.

Endorsement of Certificate (As before ~~or None~~)

Nature of Present Survey: ~~(At least)~~ in dry dock)

Docking; damage repairs; supply of anchor cable and bower anchor.

Recommendation: SUBMITTED record of 'DS 12,58' be assigned as recommended SUBJECT to set in shell plates G.7 & 8 etc. (p.s.f) being examined and dealt with as necessary by the S.S., without other condition.


DS 12,58. Subject,  
Without.

S.R.L. APPENDIX.

Keel plates in way of Nos. 3 & 4 cargo tanks slightly set up.

OFFICE NOTE.

Deck and bottom shell stiffened - Shl. 10,52.  
Docking brackets fitted - Fal. 7,53.



© 2020

Lloyd's Register  
Foundation