

The class is subject to the main discharge valve being examined and dealt with upon the vessel's return to the United Kingdom.

4E

19 JAN 1959

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....
SHIP'S NAME..... BEECHER ISLAND..... REPORT..... No. 7038
Ham
Fal 13409


MBS due 12.58, now held.

CS Advanced. Docking. Tailshaft seen.

SRL: The above items dealt with.

Some damage repairs effected to the inboard turbo generator and some tubes renewed in the port and starboard main boilers.

IT IS SUBMITTED this vessel is eligible to remain as classed with fresh records of MBS 12.58 and TS (CL) 12.58 without special condition.



Lloyd's Register
Foundation

12.1.59 00457-002464-0068