

Empire Cowdrey.

Submitted the Sld Surveyors be advised that as the certificate forwarded does not indicate thereon all the tests required by the Rules. it is considered that in this and all future similar cases the information should be obtained from the makers of the dynamo.

The certificate has been requested by telephone, and will be forwarded in due course. The tests are stated to be satisfactory.

Thus

27.11.14

© 2020

Lloyd's Register
Foundation

sls, do Sld 8/12