

Rpt. 8

Port FALMOUTH No. 14023  
Date of writing Report 18th July, 1961 When handed in at Local Office \_\_\_\_\_ Received London \_\_\_\_\_  
Survey held at River Fal No. of Visits 1 First Date and 19 Last Date 10th July 61.

## REPORT OF SHIP SURVEYS AND REPAIRS

(The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B. 05068 S.S. "BRITISH SUCCESS" Tons gross 8222  
on the Iron or Steel M.S. \_\_\_\_\_  
Built at Glasgow By Whom Blythswood S.B. Co. Ltd. Year 1946 Month 2  
Owners BP Tanker Co. Ltd. Owners' address \_\_\_\_\_  
Managers \_\_\_\_\_ (If not already in R.B.)  
Port of Registry London  
Surveyed Afloat or in Drydock Afloat Name of Dock River Fal anchorage Date of last examn. in Drydock \_\_\_\_\_

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No. 13648 Port Fal.  
To be filled in at Head Office.

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

Give dates and references to any letters relating to this Report \_\_\_\_\_

SHIP'S CLASS		Machinery	
Date of Special and of Drydocking Surveys, etc.			
*100 A1 Oil tanker		*LMC-CS	4.55
SS	4.55	d	11.59
DS	6.57	TS(CL)	8.56
		SPS	4.55

In damage cases where the Surveyor has not made a special damage report he should state whether he offered

his services for this purpose and to whom and why they were declined \_\_\_\_\_ Freeboard as marked on ship and now verified \_\_\_\_\_ ft \_\_\_\_\_ ins

Was a damage report made by anyone else? If so, by whom? \_\_\_\_\_

EXAMINATION AND REPAIRS AS PER RULE FOR TOWING TO PORT IN U.K. IN BALLAST TO BE BROKEN UP

The ship afloat, the shell plating above waterline, decks, hatch and vent coamings, super structures, and casings and all closing appliances, windlass and bower anchors examined and considered satisfactory for the intended voyage.

The Owners stated that the ship would be towed without main engines or auxiliary power on board and that it was understood that the towing arrangements were not the responsibility of the Society.

Copy of Interim Certificate attached.

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed .....								
Removed and Faird or Repaired .....								
Faird or Repaired in place .....								

Has a Survey also been held on machinery of the Ship? no

Is Classification Certificate required? If so, to be sent to \_\_\_\_\_

If so, is the Report sent now, or when will it be sent? \_\_\_\_\_

Has Interim Certificate been issued? \_\_\_\_\_

### GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:— "to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1.55"; or "to remain as Classed and to have record of drydocking 1.55, and the notation of S.S. . . . 1.55".

This ship so far as now seen is eligible to be towed to a port in the U.K. in ballast, to be broken up.

K. A. Adamson  
Surveyor to Lloyd's Register of Shipping

K. A. ADAMSON.

Date of Committee \_\_\_\_\_

MONDAY 31 JUL 1961

Minute \_\_\_\_\_

Deferred  
(Retain 'Laid up - surveys overdue 4.55')

20m, 4.61 T. (MADE AND PRINTED IN ENGLAND)

White Fal.

Noted  
for  
Header

002477-002484-0212



© 2020

Lloyd's Register  
Foundation



