

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, Fen. London

Telephone: ROYal 9166

7th January, 1958.

n. (H)

Dear Sirs,

s.s. "BADARPUR".

I shall be glad if you will kindly let me know what arrangements have now been made for the ship to be examined in drydock and for the conditions of class to be dealt with.

The class is subject to the bottom, propeller and fastenings being examined for grounding at the next drydocking; to the sternframe (E.W. 5,54) and top section of the rudder steadiment bearing being specially examined and dealt with as necessary at the next drydocking, also to indented side shell plating etc in way of after cofferdam (starboard side) being dealt with as necessary at the next drydocking by January, 1958.

I take this opportunity to point out that the Main and Auxiliary Boiler Surveys become due in February and the Special Survey in March next.

Yours faithfully,

Clerk to the
Classification Committee.

Messrs. Burmah Oil Co. (Tankers) Ltd.,
Britannic House,
Finsbury Circus,
LONDON, E.C.2.



© 2020

Lloyd's Register
Foundation

002485-002489-0096