

Surveyors.....

Received from Chief Surveyors.....

IME

BRITISH CAVALIER

REPORT

No.....


For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

Survey..... When due.....

DBS due 7.57.

IT IS SUBMITTED that, should one or more Donkey Boilers be required under steam for manoeuvring and anchoring purposes on this proposed voyage in tow as a hulk, then the required Donkey Boilers should be surveyed throughout, safety valves adjusted under steam, and windlass and steering engines tested ^{OUT}_A under full working conditions.



1.5.59



© 2020

Lloyd's Register
Foundation

002490-002497-0053