

10 APR 1961

SHIP'S NAME "BRITISH MIGHT" REPORT SNG No. 14583

EA

standing Conditions of Class: SUBJECT to sternframe at outer, (E.W.7,59) being specially examined, and to shell plates H.4, J.4 & 5 (p.s.f) and H.8, J.7 and K.7 (s.s.a), also to holed 'A' strake plate in way of after main pump room(p.s)being specially examined and dealt with as necessary, next drydocking.

L. Appendix. (~~As before or~~ None)re of Present Survey: (Afloat ~~and in drydock~~)

Temporary wear and tear repairs to fractured plating.

Recommendation:

SUBMITTED the ship is eligible to remain as classed, subject as above and to fractured butt of shell plate B.6/7 (p.s) and also shell plate in 'C' strake (s.s) in way of pump room being specially examined and dealt with as necessary next drydocking.

As Now Subject.



© 2020

Lloyd's Register
Foundation

002490-002497-0132

2.5.e
7/4/61

A