


"EMPIRE MACKAY"

F. Rpt. Gls. No. 67629.

In reply to their letter of the 2nd instant the Surveyors should be referred to the third paragraph from the bottom of Circular 1551 and informed that in this case the lengths of the poop and bridge for record purposes are governed by the positions of the freeing ports in the side plating.

According to the plan of flight deck side supports, as fitted, the actual enclosed length of the bridge extends from the forward edge of the freeing port at frame 111 to the after edge of the freeing port at frame 128 and that of the poop from the after perpendicular to the after edge of the freeing port at frame 39.



1.c.8
8, 11. 43. *[Signature]*
Lloyd's Register
Foundation

002498 - 002505 - 0237