

4E

Subject to

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor... 29 DEC 1959

NAME..... BRITISH TRADITION..... REPORT Sou..... No. 25863.....

ABS due 10.58 partly held now. The Surveyor reports a number of plain tubes in the port boiler now fitted with stoppers and the Surveyor recommends that the Class be made subject to the defective boiler tubes in the port donkey boiler being renewed by completion of the boiler survey and before the ship is recommissioned.

IT IS SUBMITTED this vessel is eligible to remain as classed with fresh record of ABS 11.59 when the survey has been completed as per this report subject as recommended.



J.V.

© 2020

24.12.59

Lloyd's Register
Foundation

002498 - 002505 - 0263