

Port of Newcastle - on - Tyne.
5-10 1956

REPORT ON MASTS, SPARS, AND RIGGING

Having, in accordance with your instructions,
 examined the Masts, Spars, Iron Work of same, and Rigging, of the
 of Vessel) British Lancer

(Date of examination) Friday October 5th 1956

I have to report that I found The Fore Stay in Poor Condition
Third Stay on Starboard Side of Foremast in Poor Condition
Remainder of Foremast Rigging in Good Condition
Foretopmast Rigging Good Condition except Starboard Backstay
in Condition. The Foretopmast Steel Tubular in
Condition and Telescopic. The Rigging on Midship
on Port in Good Condition.
Mainmast Rigging on Port side in Poor Condition
Fourth Stay on Starboard Side in Poor Condition the remainder
in Good Condition. The Mainmast Backstays Port +
in Poor Condition. Mainmast Steel Tubular + Telescopic

W. B. Horne

1 : 0 : 0

Surveyors,
 Lloyd's Register of Shipping,
NEWCASTLE.



© 2021

Lloyd's Register
 Foundation

002529-002535-0055