

2 E

Engineer Surveyor

Received from Chief Engineer Surveyor

15 MAR 1957

ME

BRITISH LANCER

REPORT

Two

No. 114024

due 11.56 partly held as CS now completed.
 " 1/57 now held.

and the following repairs carried out (due to):-

3 existing boilers now removed and 2 new D.E. Boilers
 fitted - some repairs made to M.E. Thrust.
 Salt, Fresh water and Lub. oil pumps renewed.
 new 93 Kw Steam generator fitted replacing ^{one} existing 20 Kw.
 10 Kw diesel generator found defective, new 75 Kw Diesel
 generator fitted

IT IS SUBMITTED the vessel is eligible to remain as classed.

with RECORD of survey + LMC CS 12.56 + DBS 12.56 as recommended.
 class 2032 complied with.

B. Delete all existing particulars
 of Bunkery Boilers and
 insert

2 DB (180 lb)
 + NDB (2) 12.56



© 2021

Lloyd's Register
 Foundation

002529-002535-0059