

ere the Surveyor has not made a special damage report he should state whether he offered
this purpose and to whom and why they were declined.....

Freeboard as marked on ship and now verified.....

Received from Chief Ship Surveyor.....

26 JAN 1959

"RED BANK"

REPORT

Fal.

No.

13414

Conditions of Class:

NONE.

f Certificate (~~As before~~ or None)

sent Survey: (~~Afloat~~ and in dry dock)

repairs to damage - cause not stated.

on: SUBMITTED record of 'DS 12,58' be assigned
as recommended, subject to sternframe solepiece
(E.W. & reinforced 12,58& previously) being specially
examined at the next drydocking.

Subject

OTE

bottom plating reinforced - Nwc. 12,52.
brackets fitted - Fal. 9,53.



© 2021 C.S.S. Records Dept.

to note.

Lloyd's Register
Foundation

002529-002535-0290

docking survey 12,58 subject to sternframe solepiece, (EW and reinforced 12
previously being specially examined at the next drydocking