



S.T. BURFELL

Grimisby Report No 27838.

Repairs in way of outer plate.

Fracture approx. 8" long x $\frac{1}{4}$ " deep (P+S) need out & E.W.



© 2020

Lloyd's Register
Foundation

002536-002542-0107