


S.T. STURDABERG

Grinsby Report No. 27836.

Repairs to boiler saturated steam safety valve chest.



Fracture through web approximately $2\frac{1}{2}$ " long.
Repaired by "Key-Cast", similar to "Metalock" type of
repair.



© 2020

Lloyd's Register
Foundation

002536-002542-0108