

SHIP'S NAME "BURMAH SAPPHIRE" REPORT CAL. No. 20376

EA

Outstanding Conditions of Class: SUBJECT to indented forecastle sheerstrake plating (p.s.f) being examined and dealt with as necessary by the S.S., and to indented keel plate No.2 from fwd. and shell plates E.13, F.12, 13 & 14 (s.s.f) and G.7 (s.s.a), G.14 (p.s.f) and indented shell plating and internals in way of No.1 summer tank and No.1 cargo oil tank (s.s) all being specially examined and dealt with as necessary next drydocking, and to set up bottom shell plating and internals etc. being specially examined and dealt with as necessary by 11, 61, ~~xxx~~ only homogeneous cargoes being carried with pump room or cofferdam separation between each group of cargo tanks meanwhile. S.R.L. Appendix. (~~As before~~ None) ACTION is DEFERRED for examination in dry dock after grounding.

Nature of Present Survey: (~~At sea~~ in dry dock)

Docking:- Examination of grounding damage - repairs deferred.
Part permanent repairs on account of collision damage.
Examination of the above subject items.

Recommendation:

SUBMITTED record of DS 10,61 be assigned, subject to indented forecastle sheerstrake plating (p.s.f) being examined and dealt with as necessary by the S.S., and to indented keel plate No.2 from fwd. and shell plates E.13, F.12, 13 & 14 (s.s.f) and G.7 (s.s.a), G.14 (p.s.f) also set up bottom shell plating and internals etc., also to indented shell plating and internals in way of No.1 summer tank and No.1 cargo oil tank (s.s) being specially examined and dealt with as necessary next drydocking, only homogeneous cargoes being carried with pump room or cofferdam separation between each group of cargo tanks meanwhile, also to collision damage repairs (p.s.f) being completed by 12, 61.

DS 10,61 Subject
Amended.

DELETE FROM S.R.L.

Drydocking (grounding).

Blk (new)

002536-002542-0151

Lloyd's Register
Foundation