

1 E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SHIP'S NAME "BURMAH SAPPHIRE"

REPORT

Nwc

110702

Mch

No. 15203

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine Oil Engine 2SCSA

4 cylinder 23 $\frac{5}{8}$ " - 91.5/16"

New MN 700

~~If Boilers fitted with forced draught.~~

Tail Shaft. If fitted with a continuous liner Yes

If fitted with an outside gland of approved type No

The torsional vibration characteristics of the main propelling machinery were approved in the Secretary's letter of 30.9.53. for a service speed of 109 rpm.

Similar calculations for the 80 KW generator sets were approved in the Secretary's letter of 26.11.51. for a service speed of 500 rpm.

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

\*LMC 8,53

"Carrying Petroleum in Bulk"

2 DB 150 lb.

© 2020  
1,10.53.Lloyd's Register  
Foundation

002536-002542-0165